



Sky High

Count On Us

Client: Cambourne Parish Council
Project: 9268 Cambourne
Site: 1- Jevons Lane
Survey Date: Thursday 15th May 2014
Survey Period: 07:00-19:00
Method: Video Observation
AM Weather: Hot & Clear
PM Weather: Hot & Clear

Incidents / Observations:

There were no incidents reported over the survey period.



Client : Cambourne Parish Council
 Project : 9268 Cambourne
 Site : 1- Jevons Lane
 Date : Thursday 15th May 2014

AM Weather: Hot & Clear
 PM Weather: Hot & Clear

Jevons Lane Survey

	Northbound								Southbound								Totals
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	
07:00	15	1	0	0	1	0	4	21	3	1	0	0	0	0	0	4	25
07:15	17	2	0	0	1	2	0	22	3	0	0	0	0	0	0	3	25
07:30	22	1	0	0	0	0	0	23	1	2	0	0	1	0	0	4	27
07:45	33	1	1	0	4	0	3	42	9	2	0	0	0	0	0	11	53
1 Hr	87	5	1	0	6	2	7	108	16	5	0	0	1	0	0	22	130
08:00	43	0	0	0	2	0	4	49	11	1	0	0	0	0	0	12	61
08:15	49	2	0	0	1	0	3	55	9	2	0	0	0	0	0	11	66
08:30	45	2	0	0	1	0	5	53	13	4	0	0	0	1	0	18	71
08:45	23	3	0	0	1	0	0	27	23	2	1	0	0	1	0	27	54
1 Hr	160	7	0	0	5	0	12	184	56	9	1	0	0	2	0	68	252
09:00	16	2	0	0	1	1	0	20	12	2	0	0	0	0	0	14	34
09:15	6	1	0	0	0	0	0	7	8	3	0	0	1	0	0	12	19
09:30	15	1	1	0	1	2	1	21	8	1	0	0	0	0	0	9	30
09:45	5	4	0	0	2	0	1	12	5	2	0	0	0	0	1	8	20
1 Hr	42	8	1	0	4	3	2	60	33	8	0	0	1	0	1	43	103
10:00	8	2	0	0	2	0	0	12	5	1	0	0	0	0	0	6	18
10:15	8	3	0	0	2	0	1	14	6	2	0	0	0	0	0	8	22
10:30	9	2	0	0	1	0	0	12	11	6	0	0	0	0	0	17	29
10:45	13	2	0	0	1	0	0	16	8	1	0	0	0	0	0	9	25
1 Hr	38	9	0	0	6	0	1	54	30	10	0	0	0	0	0	40	94
11:00	9	2	0	0	2	0	0	13	3	2	0	0	0	0	0	5	18
11:15	7	1	0	0	2	1	0	11	7	1	0	0	0	0	0	8	19
11:30	3	4	0	0	1	0	0	8	3	3	0	0	0	0	0	6	14
11:45	11	1	0	0	1	0	0	13	9	0	0	0	0	0	0	9	22
1 Hr	30	8	0	0	6	1	0	45	22	6	0	0	0	0	0	28	73
12:00	6	3	0	0	2	0	0	11	10	1	0	0	0	0	0	11	22
12:15	8	2	0	0	1	0	0	11	12	1	0	0	0	0	0	13	24
12:30	4	1	0	0	1	0	0	6	7	1	0	0	0	0	0	8	14
12:45	13	0	0	0	2	0	0	15	11	1	0	0	0	0	0	12	27
1 Hr	31	6	0	0	6	0	0	43	40	4	0	0	0	0	0	44	87
6 Hours	388	43	2	0	33	6	22	494	197	42	1	0	2	2	1	245	739

Northbound	Southbound
Pedestrians	Pedestrians
0	0
1	1
1	2
4	2
6	5
16	1
28	3
17	14
24	12
85	30
6	7
0	2
0	1
4	1
10	11
3	2
5	2
1	0
1	4
2	4
2	5
3	5
10	2
17	16
2	2
0	2
1	1
2	1
5	6
133	76

	Northbound								Southbound								Totals
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	
13:00	11	3	0	0	1	0	0	15	10	3	0	0	0	0	0	13	13
13:15	15	4	0	0	2	0	0	21	7	0	0	0	0	0	0	7	7
13:30	9	0	0	0	0	0	0	9	5	2	0	0	0	0	0	7	7
13:45	4	2	0	0	2	0	0	8	13	3	0	0	0	0	0	16	16
1 Hr	39	9	0	0	5	0	0	53	35	8	0	0	0	0	0	43	43
14:00	8	0	0	0	0	0	0	8	10	2	0	0	2	1	0	15	23
14:15	7	0	0	0	2	0	0	9	16	2	0	0	0	0	0	18	27
14:30	24	2	0	0	1	0	2	29	18	0	0	0	0	0	0	18	47
14:45	28	2	0	0	1	0	2	33	10	1	0	0	0	0	0	11	44
1 Hr	67	4	0	0	4	0	4	79	54	5	0	0	2	1	0	62	141
15:00	10	1	0	0	2	0	1	14	33	0	0	0	0	0	0	33	47
15:15	15	0	0	0	5	1	0	21	23	2	0	0	0	0	1	26	47
15:30	7	2	0	0	2	0	1	12	17	1	0	0	1	0	1	20	32
15:45	14	3	0	0	1	0	1	19	23	3	0	0	1	0	1	28	47
1 Hr	46	6	0	0	10	1	3	66	96	6	0	0	2	0	3	107	173
16:00	9	0	1	0	2	0	0	12	15	0	1	0	0	0	0	16	28
16:15	13	0	0	0	0	0	0	13	29	1	0	0	0	0	1	31	44
16:30	21	0	0	0	1	0	1	23	22	1	0	0	0	0	0	23	46
16:45	14	1	0	0	1	0	0	16	27	2	0	0	0	0	0	29	45
1 Hr	57	1	1	0	4	0	1	64	93	4	1	0	0	0	1	99	163
17:00	13	1	0	0	0	0	1	15	24	1	0	0	0	0	1	26	27
17:15	10	5	0	0	1	0	0	16	20	1	0	0	0	0	1	22	23
17:30	17	0	0	0	0	0	0	17	35	1	0	0	0	0	0	36	36
17:45	11	2	1	0	1	0	0	15	23	1	0	0	0	2	2	28	32
1 Hr	51	8	1	0	2	0	1	63	102	4	0	0	0	2	4	112	118
18:00	20	1	0	0	0	0	2	23	32	1	0	0	0	0	0	33	56
18:15	21	1	0	0	1	0	0	23	30	2	0	0	0	0	1	33	56
18:30	14	1	0	0	1	1	1	18	15	0	0	0	0	0	1	16	34
18:45	17	0	0	0	1	0	1	19	24	2	0	0	0	0	5	31	50
1 Hr	72	3	0	0	3	1	4	83	101	5	0	0	0	0	7	113	196
6 Hours	332	31	2	0	28	2	13	408	481	32	1	0	4	3	15	536	834

Northbound	Southbound
Pedestrians	Pedestrians
2	5
3	0
2	1
1	0
8	6
4	3
5	0
1	3
21	3
31	9
15	4
41	29
2	1
5	4
63	38
4	13
0	3
16	5
4	8
24	29
5	4
7	8
9	4
6	3
27	19
8	8
6	5
10	8
7	8
31	29
184	130

Total	720	74	4	0	61	8	35	430	678	74	2	0	6	5	16	781	1573
-------	-----	----	---	---	----	---	----	-----	-----	----	---	---	---	---	----	-----	------

Total	317	206
-------	-----	-----



Sky High

Count On Us

Client: Cambourne Parish Council
Project: 9268 Cambourne
Site: 2- Back Lane
Survey Date: Thursday 15th May 2014
Survey Period: 07:00-19:00
Method: Video Observation
AM Weather: Hot & Clear
PM Weather: Hot & Clear

Incidents / Observations:

There were no incidents reported over the survey period.



Client : Cambourne Parish Council
 Project : 9268 Cambourne
 Site : 2- Back Lane
 Date : Thursday 15th May 2014

AM Weather: Hot & Clear
 PM Weather: Hot & Clear

Back Lane Survey

Northbound									Southbound									Totals
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total			
07:00	55	7	0	0	0	0	62	17	17	0	1	0	0	0	35	97		
07:15	82	3	0	0	0	2	89	21	14	0	1	1	0	0	37	126		
07:30	80	2	1	1	0	0	85	19	9	0	0	0	0	0	28	113		
07:45	85	3	0	1	1	0	93	16	5	1	0	0	0	0	22	115		
1 Hr	87	5	1	0	6	2	108	16	5	0	0	1	0	0	22	130		
08:00	77	6	0	1	0	0	85	32	10	2	1	0	0	0	45	130		
08:15	56	5	1	0	0	0	64	40	7	0	2	0	0	4	53	117		
08:30	78	3	0	1	1	1	86	20	5	0	1	0	0	9	35	121		
08:45	64	1	0	4	0	0	72	20	5	1	0	0	0	1	27	99		
1 Hr	160	7	0	0	5	0	184	56	9	1	0	0	2	0	68	252		
09:00	54	2	0	0	0	0	58	26	2	0	1	0	0	0	29	87		
09:15	54	0	1	0	0	1	56	18	10	0	0	0	0	0	28	84		
09:30	21	3	1	0	0	0	26	26	3	3	0	0	0	0	32	58		
09:45	26	6	2	0	0	0	35	13	4	0	0	0	0	0	17	52		
1 Hr	42	8	1	0	4	3	60	33	8	0	0	1	0	1	43	103		
10:00	21	4	2	0	0	0	27	16	4	1	0	0	0	0	21	48		
10:15	35	1	1	0	0	0	39	16	11	2	1	0	0	0	30	69		
10:30	30	5	0	0	0	0	36	15	5	1	1	0	0	3	25	61		
10:45	23	3	0	2	0	0	28	12	4	3	1	0	0	0	20	48		
1 Hr	38	9	0	0	6	0	54	30	10	0	0	0	0	0	40	94		
11:00	17	5	2	1	0	1	26	9	4	1	0	0	0	0	14	40		
11:15	17	7	0	0	0	0	24	19	1	1	2	0	0	0	23	47		
11:30	21	4	2	0	0	0	27	15	2	0	3	0	0	0	20	47		
11:45	26	2	0	0	0	0	28	21	2	0	1	0	0	1	25	53		
1 Hr	30	8	0	0	6	1	45	22	6	0	0	0	0	0	28	73		
12:00	33	5	2	1	0	0	43	33	8	3	0	0	0	1	45	88		
12:15	21	4	0	1	0	0	26	11	4	0	0	0	0	0	15	41		
12:30	34	5	2	0	0	0	41	20	5	1	0	0	0	0	26	67		
12:45	31	4	1	0	0	0	36	21	5	0	0	0	0	0	26	62		
1 Hr	31	6	0	0	6	0	43	40	4	0	0	0	0	0	44	87		
6 Hours	388	43	2	0	33	6	494	197	42	1	0	2	2	1	245	739		

Northbound	Southbound
Pedestrians	Pedestrians
2	1
3	2
1	2
3	5
9	10
3	11
5	26
1	7
6	6
15	50
8	1
7	3
4	0
0	0
19	4
6	3
0	2
0	0
2	0
8	5
0	1
1	5
2	14
1	1
4	21
8	2
0	0
3	0
1	3
12	5
67	95

Northbound									Southbound									Arm Totals
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total			
13:00	32	9	0	0	0	0	41	26	7	0	1	0	1	0	35	76		
13:15	20	6	0	1	0	0	27	24	6	2	0	0	0	0	32	59		
13:30	26	3	2	1	0	0	33	29	3	3	0	0	0	0	35	68		
13:45	26	3	2	0	0	0	32	21	3	1	0	0	0	0	25	57		
1 Hr	39	9	0	0	5	0	53	35	8	0	0	0	0	0	43	103		
14:00	20	5	1	0	0	1	27	24	1	2	0	0	0	0	27	54		
14:15	24	3	1	0	0	0	30	16	7	1	0	0	0	1	25	55		
14:30	28	0	1	0	0	0	30	44	6	0	0	0	0	3	53	83		
14:45	27	9	1	0	0	0	37	54	5	0	0	0	0	6	65	102		
1 Hr	67	4	0	0	4	0	79	54	5	0	0	2	1	0	62	141		
15:00	52	5	0	0	0	3	60	23	2	1	0	0	0	1	27	87		
15:15	40	5	1	0	1	0	54	33	4	0	1	1	0	2	41	95		
15:30	35	6	1	1	0	0	43	37	4	1	0	2	0	0	44	87		
15:45	29	9	0	1	0	0	40	44	3	1	0	0	0	2	50	90		
1 Hr	46	6	0	0	10	1	66	96	6	0	0	2	0	3	107	173		
16:00	50	8	5	0	0	0	63	37	5	0	0	0	0	3	45	108		
16:15	37	9	1	0	0	1	50	39	9	0	0	0	0	0	48	98		
16:30	0	0	0	0	0	0	0	0	0	0	0	0	1	0	1	1		
16:45	0	0	0	0	0	0	1	0	0	0	0	0	2	0	2	3		
1 Hr	57	1	1	0	4	0	64	93	4	1	0	0	0	1	99	163		
17:00	38	9	0	0	0	0	47	52	4	0	0	0	0	2	58	105		
17:15	33	4	0	0	0	3	40	72	4	0	0	0	0	0	76	116		
17:30	39	5	0	0	0	4	48	74	7	0	0	0	0	2	83	131		
17:45	41	4	0	0	0	0	45	64	5	0	0	0	1	2	72	117		
1 Hr	51	8	1	0	2	0	63	102	4	0	0	0	2	4	112	118		
18:00	38	5	0	0	0	1	45	68	2	0	0	0	0	1	71	116		
18:15	26	2	0	0	0	0	28	66	6	0	0	0	0	4	76	104		
18:30	30	1	0	0	0	0	31	75	5	1	0	0	0	2	83	114		
18:45	38	3	0	0	0	1	42	56	3	0	0	0	0	3	62	104		
1 Hr	72	3	0	0	3	1	83	101	5	0	0	0	0	7	113	196		
6 Hours	332	31	2	0	28	2	408	481	32	1	0	4	3	15	536	834		
Total	720	74	4	0	61	8	902	678	74	2	0	6	5	16	781	1573		

Northbound	Southbound
Pedestrians	Pedestrians
0	0
0	4
0	0
2	2
2	6
1	0
1	1
0	0
2	7
4	8
1	8
41	0
22	5
8	9
72	22
0	2
4	2
0	0
0	0
4	4
5	6
2	8
4	4
1	2
12	20
7	3
3	0
0	5
1	5
11	13
105	73
172	168



Sky High

Count On Us

Client: Cambourne Parish Council
Project: 9268 Cambourne
Site: 3- Lancaster Gate
Survey Date: Thursday 15th May 2014
Survey Period: 07:00-19:00
Method: Video Observation
AM Weather: Hot & Clear
PM Weather: Hot & Clear

Incidents / Observations:

There were no incidents reported over the survey period.



Client : Cambourne Parish Council
 Project : 9268 Cambourne
 Site : 3- Lancaster Gate
 Date : Thursday 15th May 2014

AM Weather: Hot & Clear
 PM Weather: Hot & Clear

Lancaster Gate Survey

	Northbound								Southbound								Totals
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	
07:00	38	2	0	0	0	0	2	42	17	9	0	1	0	0	6	33	75
07:15	54	2	0	0	0	2	1	59	20	12	0	0	0	0	2	34	93
07:30	57	2	0	1	1	1	5	67	21	10	0	1	0	0	4	36	103
07:45	55	2	0	1	0	0	7	65	20	4	0	0	1	0	2	27	92
1 Hr	204	8	0	2	1	3	15	233	78	35	0	2	1	0	14	130	363
08:00	54	5	0	0	0	0	6	65	32	12	1	0	0	0	7	52	117
08:15	41	5	0	0	0	0	6	52	61	7	1	1	0	0	20	90	142
08:30	83	5	0	2	0	0	39	129	37	4	0	1	0	0	26	68	197
08:45	61	1	0	2	0	0	16	80	17	5	0	0	0	0	6	28	108
1 Hr	239	16	0	4	0	0	67	326	147	28	2	2	0	0	59	238	564
09:00	30	3	0	0	0	0	0	33	17	3	1	0	0	0	1	22	55
09:15	27	2	1	0	0	0	0	30	13	5	0	0	0	0	2	20	50
09:30	14	1	0	0	0	0	0	15	15	4	3	0	0	0	1	23	38
09:45	10	8	0	0	0	0	1	19	11	3	0	0	0	0	0	14	33
1 Hr	81	14	1	0	0	0	1	97	56	15	4	0	0	0	4	79	176
10:00	14	3	1	1	0	0	0	19	13	4	1	0	0	0	1	19	38
10:15	17	1	1	0	0	0	1	20	7	9	0	1	0	0	0	17	37
10:30	17	4	1	0	0	0	0	22	10	4	2	1	0	0	3	20	42
10:45	17	5	0	2	0	0	2	26	13	2	3	1	0	0	1	20	46
1 Hr	65	13	3	3	0	0	3	87	43	19	6	3	0	0	5	76	163
11:00	7	3	1	1	0	0	2	14	10	3	1	0	0	0	1	15	29
11:15	9	2	1	0	0	0	2	14	11	1	1	1	0	0	3	17	31
11:30	15	1	1	0	0	0	3	20	12	1	1	1	0	0	1	16	36
11:45	22	2	0	0	0	0	1	25	15	4	0	1	0	0	1	21	46
1 Hr	53	8	3	1	0	0	8	73	48	9	3	3	0	0	6	69	142
12:00	19	3	2	0	0	0	6	30	25	5	1	0	0	0	5	36	66
12:15	11	3	0	1	0	0	0	15	8	6	0	0	0	0	1	15	30
12:30	21	6	1	0	0	0	2	30	10	3	0	0	0	0	1	14	44
12:45	16	10	0	0	0	0	0	26	15	6	0	0	0	0	2	23	49
1 Hr	67	22	3	1	0	0	8	101	58	20	1	0	0	0	9	88	189
6 Hours	709	81	10	11	1	3	102	917	430	126	16	10	1	0	97	680	1597

Northbound	Southbound
Pedestrians	Pedestrians
4	2
8	3
6	0
36	6
54	11
2	7
13	67
66	20
50	20
131	114
8	11
8	4
4	3
3	4
23	22
5	2
10	6
5	2
2	3
22	13
7	3
5	2
9	10
12	15
33	30
6	8
6	9
6	8
3	10
21	35
284	225

	Northbound								Southbound								Arm Totals
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	
13:00	12	10	0	0	0	0	1	23	14	7	1	0	0	0	1	23	46
13:15	15	2	0	1	0	0	2	20	18	5	1	1	0	0	0	25	45
13:30	16	3	1	1	0	0	0	21	19	2	2	0	0	0	0	23	44
13:45	14	0	2	0	0	0	1	17	13	3	0	0	0	0	0	16	33
1 Hr	57	15	3	2	0	0	4	81	64	17	4	1	0	0	1	87	168
14:00	11	5	1	0	0	0	0	17	22	3	1	0	0	0	1	27	44
14:15	10	4	0	0	0	0	2	16	11	0	0	0	0	0	0	11	27
14:30	14	3	0	0	0	0	5	22	31	4	0	0	0	0	1	36	58
14:45	17	11	0	0	0	0	3	31	69	4	0	0	0	0	16	89	120
1 Hr	52	23	1	0	0	0	10	86	133	11	1	0	0	0	18	163	249
15:00	48	4	1	0	0	0	20	73	19	1	1	0	0	0	11	32	105
15:15	50	2	1	0	1	0	16	70	29	2	0	1	1	0	25	58	128
15:30	24	6	1	0	0	0	5	36	23	0	1	0	1	0	7	32	68
15:45	23	8	0	1	0	0	2	34	36	2	1	0	0	0	3	42	76
1 Hr	145	20	3	1	1	0	43	213	107	5	3	1	2	0	46	164	377
16:00	45	7	1	0	0	0	2	55	29	2	1	0	0	0	5	37	92
16:15	20	7	2	0	0	0	1	30	19	3	0	0	0	0	4	26	56
16:30	23	4	0	0	0	0	4	31	24	2	0	0	0	1	2	29	60
16:45	24	20	1	0	0	0	2	47	26	3	0	0	0	0	5	34	81
1 Hr	112	38	4	0	0	0	9	163	98	10	1	0	0	1	16	126	289
17:00	22	4	0	0	0	0	1	27	38	1	0	0	0	1	4	44	71
17:15	23	5	0	0	0	0	6	34	45	2	0	0	0	0	4	51	85
17:30	18	4	0	0	0	0	5	27	53	6	0	0	0	0	2	61	88
17:45	28	3	0	0	0	0	4	35	48	1	0	0	0	1	2	52	87
1 Hr	91	16	0	0	0	0	16	123	184	10	0	0	0	2	12	208	331
18:00	31	2	0	0	0	0	6	39	96	8	0	0	0	0	4	108	147
18:15	18	2	0	0	0	0	3	23	51	2	0	0	0	0	6	59	82
18:30	14	2	0	0	0	0	2	18	56	2	1	0	0	0	5	64	82
18:45	19	3	0	0	0	0	6	28	40	2	0	0	0	0	1	43	71
1 Hr	82	9	0	0	0	0	17	108	243	14	1	0	0	0	16	274	382
6 Hours	539	121	11	3	1	0	99	774	829	67	10	2	2	3	109	1022	1796

Northbound	Southbound
Pedestrians	Pedestrians
11	9
3	6
9	8
3	4
26	27
3	5
2	4
6	4
12	16
23	29
47	17
62	85
7	21
16	10
132	133
7	21
7	10
6	5
8	6
28	42
4	27
17	4
10	13
10	15
41	59
9	14
6	21
6	8
22	4
43	47
293	337

Total	1248	202	21	14	2	3	201	1691	1259	193	26	12	3	3	206	1702	3393
-------	------	-----	----	----	---	---	-----	------	------	-----	----	----	---	---	-----	------	------

577	562
-----	-----



Sky High

Count On Us

Client: Cambourne Parish Council
Project: 9268 Cambourne
Site: 4- Sterling Way
Survey Date: Thursday 15th May 2014
Survey Period: 07:00-19:00
Method: Video Observation
AM Weather: Hot & Clear
PM Weather: Hot & Clear

Incidents / Observations:

There were no incidents reported over the survey period.



Client : Cambourne Parish Council
 Project : 9268 Cambourne
 Site : 4- Sterling Way
 Date : Thursday 15th May 2014

AM Weather: Hot & Clear
 PM Weather: Hot & Clear

Sterling Way

	Northbound								Southbound								Totals
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	
07:00	3	0	0	0	0	0	0	3	12	9	0	1	0	0	0	22	25
07:15	4	0	0	0	0	0	0	4	18	7	0	0	0	0	0	25	29
07:30	5	0	0	1	0	0	0	6	12	9	0	1	0	0	0	22	28
07:45	10	0	0	1	0	0	0	11	15	6	1	0	0	0	0	22	33
1 Hr	22	0	0	2	0	0	0	24	57	31	1	2	0	0	0	91	115
08:00	5	1	0	0	0	0	0	6	28	8	1	0	0	0	0	37	43
08:15	7	1	0	0	0	0	0	8	41	4	1	2	0	0	9	57	65
08:30	33	2	2	0	0	0	0	45	32	4	0	1	0	0	26	63	108
08:45	19	1	1	1	0	0	0	25	6	4	0	0	0	0	0	10	35
1 Hr	64	5	3	1	0	0	0	84	107	20	2	3	0	0	35	167	251
09:00	9	1	2	0	0	0	0	12	6	3	1	0	0	0	0	10	22
09:15	5	2	1	0	0	0	0	8	7	1	0	0	0	0	0	8	16
09:30	2	1	1	0	0	0	0	4	5	2	3	0	0	0	0	10	14
09:45	0	3	1	0	0	0	0	4	1	2	0	0	0	0	0	3	7
1 Hr	16	7	5	0	0	0	0	28	19	8	4	0	0	0	0	31	59
10:00	1	1	1	1	0	0	0	4	4	1	0	1	0	0	1	7	11
10:15	3	1	1	0	0	0	0	5	2	5	0	1	0	0	0	8	13
10:30	4	4	1	0	0	0	0	9	6	2	2	1	0	0	1	12	21
10:45	3	3	0	2	0	0	0	8	6	1	5	1	0	0	1	14	22
1 Hr	11	9	3	3	0	0	0	26	18	9	7	4	0	0	3	41	67
11:00	5	2	2	1	0	0	0	10	4	3	2	0	0	0	0	9	19
11:15	6	3	3	0	0	0	1	13	6	1	2	0	0	0	0	9	22
11:30	3	1	2	0	0	0	0	6	5	1	1	1	0	0	1	9	15
11:45	6	2	2	0	0	0	0	10	11	6	0	1	0	0	0	18	28
1 Hr	20	8	9	1	0	0	1	39	26	11	5	2	0	0	1	45	84
12:00	11	5	3	1	0	0	0	20	4	5	1	0	0	0	1	11	31
12:15	7	1	0	0	0	0	0	8	4	1	1	0	0	0	0	6	14
12:30	2	1	0	0	0	0	0	3	2	4	0	0	0	0	1	7	10
12:45	5	2	2	0	0	0	0	9	7	4	0	0	0	0	2	13	22
1 Hr	25	9	5	1	0	0	0	40	17	14	2	0	0	0	4	37	77
6 Hours	158	38	25	8	0	0	12	241	244	93	21	11	0	0	43	412	653

Northbound	Southbound
Pedestrians	Pedestrians
1	2
0	0
0	3
4	1
5	6
0	3
0	48
5	52
0	0
5	103
3	0
1	0
0	0
0	0
4	0
0	0
0	0
0	0
3	4
0	1
0	0
2	2
2	3
0	0
0	0
0	0
0	0
19	116

	Northbound								Southbound								Arm Totals
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	
13:00	6	5	0	0	0	0	0	11	4	3	1	0	0	0	0	8	19
13:15	1	2	0	1	0	0	0	4	4	3	1	1	0	0	0	9	13
13:30	8	3	1	1	0	0	0	13	2	1	2	0	0	0	0	5	18
13:45	2	1	2	0	0	0	0	5	4	1	1	0	0	0	0	6	11
1 Hr	17	11	3	2	0	0	0	33	14	8	5	1	0	0	0	28	61
14:00	4	5	2	0	0	0	0	11	2	2	2	0	0	0	0	6	17
14:15	3	2	1	0	0	0	1	7	5	0	0	0	0	0	0	5	12
14:30	1	1	0	0	0	0	1	3	17	1	0	0	0	0	0	18	21
14:45	4	6	0	0	0	0	0	12	45	5	0	0	0	0	12	62	74
1 Hr	12	14	3	0	0	0	0	33	69	8	2	0	0	0	12	91	124
15:00	33	3	0	0	0	0	16	52	10	0	1	0	0	0	3	14	66
15:15	33	4	1	0	0	0	12	50	3	2	0	1	0	0	1	7	57
15:30	8	6	1	0	0	0	4	19	5	1	2	0	0	0	1	9	28
15:45	13	7	1	1	0	0	0	22	11	1	0	0	0	0	0	12	34
1 Hr	87	20	3	1	0	0	32	143	29	4	3	1	0	0	5	42	185
16:00	28	5	1	0	0	0	1	35	12	2	1	0	0	0	1	16	51
16:15	11	6	0	0	0	0	0	17	2	0	0	0	0	0	0	2	19
16:30	6	5	0	0	0	0	0	11	2	0	0	0	0	0	2	4	15
16:45	11	15	1	0	0	0	1	28	3	2	0	0	0	0	1	6	34
1 Hr	56	31	2	0	0	0	2	91	19	4	1	0	0	0	4	28	119
17:00	14	3	0	0	0	0	3	20	3	0	0	0	0	0	4	7	27
17:15	6	2	0	0	0	0	0	8	5	0	0	0	0	0	0	5	13
17:30	6	4	0	0	0	0	0	10	1	0	0	0	0	0	0	1	11
17:45	5	1	0	0	0	0	0	6	5	0	0	0	0	0	0	5	11
1 Hr	31	10	0	0	0	0	3	44	14	0	0	0	0	0	4	18	62
18:00	6	1	0	0	0	0	2	9	10	0	0	0	0	0	3	13	22
18:15	7	1	0	0	0	0	1	9	2	0	0	0	0	0	0	2	11
18:30	3	0	0	0	0	0	0	3	9	0	1	0	0	0	0	10	13
18:45	3	0	0	0	0	0	1	4	3	2	0	0	0	0	0	5	9
1 Hr	19	2	0	0	0	0	4	25	24	2	1	0	0	0	3	30	55
6 Hours	222	88	11	3	0	0	45	369	169	26	12	2	0	0	28	237	606
Total	380	126	36	11	0	0	57	610	413	119	33	13	0	0	71	649	1259

Northbound	Southbound
Pedestrians	Pedestrians
0	0
0	1
0	1
0	2
0	4
1	3
4	0
0	2
2	0
7	5
39	0
26	0
4	1
0	1
69	2
9	2
1	1
2	4
2	2
14	9
7	5
2	1
1	0
0	2
10	8
1	4
2	1
0	0
2	2
5	7
105	35
124	151